



Copyright (c) 2009–2020 Michael Buesch

Sheet: /
File: estop.sch

Title: CNC stepper driver Emergency Stop

Size: A4 Date: 2020-01-04

KiCad E.D.A. kicad 5.1.5+dfsg1-2

Rev: 1

Id: 1/1

To pin10 of each LMD18245 on each axis (3 axis, 2 LMDs each = 6 pins)
Pulling pin10 of the LMD18245 high will short the motors.

To Master Spindle relais